



Thurston Groves HOA Monthly Waterway Inspection Report

Reason for Inspection: Routine Scheduled - Monthly

Inspection Date: 7/20/2018

Prepared for:

Mr. David Fedash, LCAM Ameri-Tech Property Management, Inc. 24701 US Highway 19 North, Suite #102 Clearwater, Florida 33763

Prepared by:

Chris Cipollina, Account Representative/Biologist

Aquatic Systems, Inc. - St. Pete Field Office

Corporate Headquarters

2100 N.W. 33rd Street, Pompano Beach, FL 33069

1-800-432-4302

Thurston Groves HOA Waterway Inspection Report

7/20/2018

Site: 1



Comments: Requires attention

Overgrowth of Primrose, Alligator Weed, and Torpedo Grass was observed throughout the literal shelf and along the perimeter of the waterway. This was targeted during the week of this inspection. This will receive a two week follow up treatment to achieve desired results.





Management Summary

The following observations were made throughout the July Account Inspection of Thurston Groves:

- Alligator Weed, Primrose Willow, and Torpedo Grass were observed within the beneficial vegetation along the perimeter and within the littoral shelf. This had been targeted during the week of this inspection, and is scheduled to receive a two week follow up treatment to ensure that desired results are achieved. The decomposition process will be closely monitored, while applying additional treatments to regrowth as observed.

- The Plecostomus populations were not observed along the homeowner's shoreline of the waterway as desired.

Recommendations/Action Items

During our upcoming scheduled visits, Aquatic Systems, Inc. will focus on the following:

- Closely monitor the decomposition of undesired vegetation along the perimeter of the waterway and within the littoral shelf.

- Apply additional spot-spray grass treatments along the perimeter of the lake and within the littoral shelf during our two week follow up treatment to ensure that desired results are achieved.

- Continue to monitor the burrowing behavior of the Plecostomus populations within the waterway.

- Clear the control structure of flow-restricting materials.
- Follow up with all previous treatments and closely monitor the results.

Aquatic Systems, Inc. will continue to care for the waterways within the Thurston Groves Community.

Aquatic Systems, Inc.

1-800-432-4302